



ASBESTOS RE-INSPECTION SURVEY REPORT

GENERAL SERVICES ADMINISTRATION
REGION 10
SAFETY AND ENVIRONMENTAL TEAM
400 15th STREET SW
AUBURN, WA 98001



CONDUCTED AT:

AUBURN ADMINISTRATION BUILDING
GSA BUILDING NUMBER WA0811KA
400 15th STREET SW
AUBURN, WASHINGTON

ASSESSMENT DATE:
10-19- 2012

PREPARED BY:
UNITED STATES PUBLIC HEALTH SERVICE
FEDERAL OCCUPATIONAL HEALTH SERVICE
DALLAS AREA OFFICE
1301 YOUNG STREET, SUITE 772
DALLAS, TX 75202



RE-INSPECTION PROJECT SCOPE

At the request of General Services Administration (GSA), Med-Tox Northwest (MTNW), representing U.S. Public Health Service Federal Occupational Health (FOH), performed a condition re-inspection of GSA's Auburn Administration Building (building number WA0811KA) located at 400 15th Street Southwest in Auburn, Washington. A visual inspection was conducted and provided a current physical assessment of previously identified asbestos-containing building materials (ACBM) and materials that were assumed asbestos-containing as identified in the May 23, 2007 EHS International, Inc. (EHSI) re-inspection report. Physical assessment data from the 2007 EHSI report was also reviewed. Material location drawings can be found in Appendix A. Copies of the current physical assessment data sheets (Asbestos Re-inspection forms) can be found in Appendix B. This re-inspection of GSA's Auburn Administration Building was performed on October 19, 2012 by FOH representative Marc Rickert of MTNW, a certified Asbestos Hazard Emergency Response Act (AHERA) building inspector. Mr. Rickert's AHERA building inspector certification is included in Appendix C.

BUILDING DESCRIPTION

The GSA Auburn Administration Building is primarily an office building with conference rooms. Interior finishes include carpet, vinyl floor tile, plaster, gypsum wallboard and acoustical ceiling tile. Exterior finishes are masonry and mortar with a flat built-up roof. Heating is provided by a hydronic system.

ASBESTOS CONTAINING MATERIALS PREVIOUSLY IDENTIFIED

As part of the scope of this re-inspection, the 2007 EHSI re-inspection report for GSA's Auburn Administration Building was reviewed. This GSA facility does contain known friable and non-friable ACM. The following table provides a summary of asbestos materials identified from the 2007 EHSI re-inspection report:

| Material | Location | Quantity | Abatement estimate |
|--|------------|--------------------|---------------------|
| 9-x 9-inch vinyl asbestos tile (VAT) under carpet with non-asbestos mastic | Throughout | 91,500 square feet | \$1.50 square foot |
| Leveling compound | Throughout | 4,000 square feet | \$2.00 square foot |
| Ductwork insulation | Throughout | 172 square feet | \$12.00 square foot |
| Gaskets | Throughout | 8 each | \$20.00 each |

| Material | Location | Quantity | Abatement estimate |
|---|---|-------------------|---------------------------|
| Pipe fittings | Throughout | 2,015 each | \$25.00 each |
| Pipe lagging | Throughout | 2,400 linear feet | \$20.00 linear foot |
| 12-x 12-inch vinyl floor tile (VFT) with non-ACM mastic over 9-x 9-inch VAT with non-ACM mastic | Room 1049, hallways south and east of cafeteria and kitchen | 1,330 square feet | \$3.00 square foot |
| Baseboard mastic | Throughout | 612 linear feet | \$6.00 linear foot |
| Elevated flooring over 9-x 9-inch VAT and non-ACM mastic on concrete | Room 1551 | 200 square feet | \$2.50 square foot |
| 9-x 9-inch VAT and non-asbestos mastic on concrete | Mechanical room 1041, 1032, 1032B, electrical closet and storage closet | 1,820 square feet | \$1.50 square foot |

Note: Unit pricing could be much higher or lower based on the quantity of material that an abatement contractor is bidding on.

Suspect ACBM may not have been previously sampled; therefore, was identified as assumed ACBM. The following table identifies assumed suspect ACBM from the 2007 EHSL re-inspection report:

| Material | Location | Quantity | Abatement estimate |
|-----------------|-----------------|-----------------|---------------------------|
| Fire door cores | Throughout | 32 each | \$150.00 each |

Note: Unit pricing could be much higher or lower based on the quantity of material that an abatement contractor is bidding on.

Suspect materials that were previously sampled and found to be non-asbestos containing as identified in the 2007 EHSI re-inspection report are identified in the following table:

| Material | Location |
|--|-----------------------------------|
| 12 x-12-inch glued-on ceiling tile* | All stairways and main lobby |
| Joint compound | Throughout |
| Debris above ceiling | Kitchen |
| Plaster walls and ceilings | Throughout |
| 12 x-12-inch vinyl floor tile and mastic | Kitchen serving area |
| Gypsum wallboard | Throughout |
| Window sealant | Throughout |
| Carpet backing and carpet mastic | Throughout |
| Fireproofing | Throughout |
| Black rubber flooring and backing | Lobby |
| 2'x2' SACT with plain pattern | Throughout |
| White sink undercoating | Kitchen and break room North wall |
| Canvas on pipe insulation | Throughout |
| Stair tread and mastic | All stairwells and landings |

*The glue was identified as an assumed ACM material in the Executive Summary in the EHSI 2007 re-inspection report; however, this material was sampled in the 2007 EHSI re-inspection report and found negative for asbestos-it was also not identified in the asbestos materials drawings.

For a complete listing of the current re-inspection assessment forms, see Appendix B.

RE-INSPECTION OBSERVATIONS

All previously identified asbestos containing materials appear to be in good to fair condition at the time of the re-inspection.

CONCLUSIONS AND RECOMMENDATIONS

The material condition should be monitored by all employees in the facility, and if any damage is identified, notification must be made to the appropriate individuals.

Based on our conclusions, FOH is making the following recommendations: Continue to monitor material condition-any damage must be repaired or cleaned by asbestos certified workers. At a minimum, asbestos awareness training should be provided to all maintenance workers as required by Federal and State regulations.

If any remodeling or demolition is to be performed, FOH recommends that a destructive inspection be performed. Destructive sampling would identify any concealed materials that may be disturbed by the project and potentially exclude materials that are presently known or assumed asbestos. Federal and State regulations require that any suspect material be treated as asbestos-containing until laboratory analysis demonstrates that it is non-asbestos. This sampling must be conducted by an accredited EPA/AHERA building inspector. The analysis must be performed by an accredited laboratory.

A copy of FOH representative Marc Rickert's AHERA building inspector certification is included in Appendix C.

LIMITATIONS

Reasonable effort was made by FOH to locate and reassess the condition of all materials identified in the EHSI re-inspection. During the current re-inspection, not all rooms or areas were accessible due to tenant restrictions. As part of this re-inspection, GSA should note that only materials defined as being suspect materials in the EHSI re-inspection were to be assessed during this re-inspection, and did not require the addressing of concealed materials within the building. The scope of work did not include verification of the original survey documents. While the assessment of these materials is not required, sampling of these materials is required by local and/or State of Washington regulations prior to renovations or demolition of a building. Destructive investigation and sampling is required prior to any renovation or demolition of the building. Failure to follow these recommendations may result in visible emissions of unknown asbestos materials resulting in regulatory citations and monetary fines; FOH cannot be held liable or responsible for failure to follow these recommendations.

This report has been prepared for the exclusive use of FOH and GSA; FOH cannot be held responsible for interpretation by others of the data contained in this report; any use of this report shall include the entire document. This re-inspection is not intended for use as abatement plans, specifications or abatement project design.

If you have any questions regarding this report or require further clarification, please do not hesitate to contact me at (253) 351-0677.

Inspected By:

A handwritten signature in black ink, appearing to read "Marc Rickert". The signature is fluid and cursive, with a horizontal line extending from the end.

Marc Rickert

AHERA Asbestos Building Inspector Certification #:13-BI-2501

Expires: 5/17/2013

Reviewed By:

A handwritten signature in blue ink, appearing to read "Ingrid M. Holznagel". The signature is cursive and somewhat stylized.

Ingrid Holznagel

Project Manager

Attachments:

Appendix A – Drawings

Appendix B – Asbestos Re-inspection Forms

Appendix C – AHERA Building Inspector Certification

APPENDIX A

DRAWINGS

BUILDING NOTES

- 1. DRAWING IS SCHEMATIC AND MATERIAL LOCATIONS FOR ASBESTOS ARE APPROXIMATE.
- 2. REFER TO REPORT FOR MORE INFORMATION ABOUT THE SAMPLED OR ASSUMED MATERIALS.
- 3. CONCEALED AND ACCESSIBLE PIPING INSULATION ON DOMESTIC AND HYDRONIC PIPING IS ASBESTOS CONTAINING.
- 4. JOINT COMPOUND IN THIS BUILDING TESTED <1% (LESS THAN 1%) ASBESTOS. WA STATE DEPARTMENT OF LABOR AND INDUSTRIES (L&I) PER WISHA REGIONAL DIRECTIVE 23.30 DATED 12/28/2000. REQUIRES DEMOLITION PERSONNEL TO BE TRAINED IN ACCORDANCE WITH WAC. 296-62-0772215.
- 5. IN ADDITION TO THE ASBESTOS CONTAINING MATERIALS SHOWN ON THIS DRAWING, THE FOLLOWING ITEMS HAVE BEEN CONFIRMED OR ARE ASSUMED TO CONTAIN ASBESTOS:
 - A. DUCTWORK INSULATION
 - B. GASKETS
 - C. BASEBOARD MASTIC


SHEET NOTES

- ① DAMAGED ASBESTOS CONTAINING TSI PIPING.

LEGEND



DAMAGED ACM MATERIAL AREA



EHS-International, Inc.
13228 NE 20th Street, Suite 100
Bellevue, Washington 98005
Ph: (425) 455-2959
Fax: (425) 646-7247

GSA - AUBURN ADMINISTRATION BUILDING
BUILDING NUMBER - WA0811KA
AUBURN, WASHINGTON
DAMAGED MATERIAL DRAWING

| | |
|------------------|--|
| PROJECT MANAGER: | J. O'MALLEY |
| INSPECTORS: | E. HUARTE C. ALVAREZ L. KOLLASCH |
| SURVEY DATE: | 3/15-16/07 |
| EHSI PROJECT # | 9143-01 |
| DRAWN BY: | ERA |
| SCALE: | NTS |
| ISSUE DATE: | |

FIRST FLOOR

DM - 1





BUILDING NOTES


1. DRAWING IS SCHEMATIC AND MATERIAL LOCATIONS FOR ASBESTOS ARE APPROXIMATE.
2. REFER TO REPORT FOR MORE INFORMATION ABOUT THE SAMPLED OR ASSUMED MATERIALS.
3. CONCEALED AND ACCESSIBLE PIPING INSULATION ON DOMESTIC AND HYDRONIC PIPING IS ASBESTOS CONTAINING.
4. JOINT COMPOUND IN THIS BUILDING TESTED <1% (LESS THAN 1%) ASBESTOS. WA STATE DEPARTMENT OF LABOR AND INDUSTRIES (L&I) PER WISHA REGIONAL DIRECTIVE 23.30 DATED 12/28/2000. REQUIRES DEMOLITION PERSONNEL TO BE TRAINED IN ACCORDANCE WITH WAC. 296-62-0772215.
5. IN ADDITION TO THE ASBESTOS CONTAINING MATERIALS SHOWN ON THIS DRAWING, THE FOLLOWING ITEMS HAVE BEEN CONFIRMED OR ARE ASSUMED TO CONTAIN ASBESTOS:
 - A. DUCTWORK INSULATION
 - B. GASKETS
 - C. BASEBOARD MASTIC

SHEET NOTES

- ① ASBESTOS CONTAINING LEVELING COMPOUND UNDER NON-ASBESTOS CONTAINING TREAD FLOORING AND MASTIC, ON CONCRETE
- ② ASBESTOS CONTAINING LEVELING COMPOUND UNDER CARPET AND NON-ASBESTOS CONTAINING CARPET MASTIC, IN ELEVATOR
- ③ CARPET SQUARES OVER 9" VINYL ASBESTOS TILE WITH NON-ASBESTOS CONTAINING MASTIC
- ④ 9" VINYL ASBESTOS TILE WITH NON-ASBESTOS CONTAINING MASTIC

LEGEND

- | | |
|---|--|
|  | ACM LEVELING COMPOUND UNDER NON-ACM FLOOR TREAD AND MASTIC |
|  | ACM LEVELING COMPOUND UNDER NON-ACM CARPET MASTIC |
|  | CARPET SQUARES OVER 9" VAT WITH NON-ACM MASTIC |
|  | 9" VAT WITH NON-ACM MASTIC |



ehsi
 EHS-International, Inc.
 13228 NE 20th Street, Suite 100
 Bellevue, Washington 98005
 Ph: (425) 455-2959
 Fax: (425) 646-7247

GSA - AUBURN ADMINISTRATION BUILDING
 BUILDING NUMBER - WA0811KA
 AUBURN, WASHINGTON
 HOMOGENEOUS MATERIAL DRAWING

PROJECT MANAGER:
 J. O'MALLEY
 INSPECTORS:
 E. HUARTE
 L. KOLLASCH
 C. ALVAREZ
 SURVEY DATE:
 3/15-16/07
 EHS PROJECT #
 9143-01
 DRAWN BY:
 ERA
 SCALE:
 NTS
 ISSUE DATE:

SECOND FLOOR

HM - 4.0

BUILDING NOTES


1. DRAWING IS SCHEMATIC AND MATERIAL LOCATIONS FOR ASBESTOS ARE APPROXIMATE.
2. REFER TO REPORT FOR MORE INFORMATION ABOUT THE SAMPLED OR ASSUMED MATERIALS.
3. CONCEALED AND ACCESSIBLE PIPING INSULATION ON DOMESTIC AND HYDRONIC PIPING IS ASBESTOS CONTAINING.
4. JOINT COMPOUND IN THIS BUILDING TESTED <1% (LESS THAN 1%) ASBESTOS. WA STATE DEPARTMENT OF LABOR AND INDUSTRIES (L&I) PER WISHA REGIONAL DIRECTIVE 2.3.30 DATED 12/28/2000. REQUIRES DEMOLITION PERSONNEL TO BE TRAINED IN ACCORDANCE WITH WAC: 296-62-0772215.
5. IN ADDITION TO THE ASBESTOS CONTAINING MATERIALS SHOWN ON THIS DRAWING, THE FOLLOWING ITEMS HAVE BEEN CONFIRMED OR ARE ASSUMED TO CONTAIN ASBESTOS:
 - A. DUCTWORK INSULATION
 - B. DUCTWORK
 - C. BASEBOARD MASTIC

SHEET NOTES

- ① ASSUMED ASBESTOS CONTAINING CORE FIRE DOOR
- ② ASBESTOS CONTAINING THERMAL INSULATION ON PIPING (INCLUDES FITTINGS)

LEGEND

- ASSUMED ACM-CORE FIRE DOOR
- ▨ ACM TSI PIPING



GSA - AUBURN ADMINISTRATION BUILDING
BUILDING NUMBER - WA0811KA
AUBURN, WASHINGTON
HOMOGENEOUS MATERIAL DRAWING

ehsi
EHS-International, Inc.
11328 NE 20th Street, Suite 100
Bellevue, Washington 98005
Ph: (425) 455-2659
Fax: (425) 946-7247



PROJECT MANAGER: J. O'MALLEY
INSPECTOR: E. HUARTE
L. KOLLASCH
C. ALVAREZ
START DATE: 3/15-16/07
END PROJECT: 9/4/3-01
DRAWN BY: ERA
SCALE: NTS
ISSUE DATE:

SECOND FLOOR

HM - 3.0

BUILDING NOTES


1. DRAWING IS SCHEMATIC AND MATERIAL LOCATIONS FOR ASBESTOS ARE APPROXIMATE.
2. REFER TO REPORT FOR MORE INFORMATION ABOUT THE SAMPLED OR ASSUMED MATERIALS.
3. CONCEALED AND ACCESSIBLE PIPING INSULATION ON DOMESTIC AND HYDRONIC PIPING IS ASBESTOS CONTAINING.
4. JOINT COMPOUND IN THIS BUILDING TESTED <1% (LESS THAN 1%) ASBESTOS. WA STATE DEPARTMENT OF LABOR AND INDUSTRIES (L&I) PER WISHA REGIONAL DIRECTIVE 23.30 DATED 12/28/2000. REQUIRES DEMOLITION PERSONNEL TO BE TRAINED IN ACCORDANCE WITH WAC. 296-62-0772215.
5. IN ADDITION TO THE ASBESTOS CONTAINING MATERIALS SHOWN ON THIS DRAWING, THE FOLLOWING ITEMS HAVE BEEN CONFIRMED OR ARE ASSUMED TO CONTAIN ASBESTOS:
A. DUCTWORK INSULATION
B. GASKETS
C. BASEBOARD MASTIC

SHEET NOTES

- ① 12" NON-ACM VINYL FLOOR TILE OVER 9" VINYL ASBESTOS TILE WITH NON ASBESTOS CONTAINING MASTIC, ON CONCRETE
- ② 9" VINYL ASBESTOS TILE WITH NON ASBESTOS CONTAINING MASTIC, ON CONCRETE
- ③ ELEVATED FLOORING OVER 9" VINYL ASBESTOS TILE WITH NON ASBESTOS CONTAINING MASTIC, ON CONCRETE
- ④ CARPET SQUARES OVER 9" VINYL ASBESTOS TILE WITH NON ASBESTOS CONTAINING MASTIC, ON CONCRETE
- ⑤ ASBESTOS CONTAINING LEVELING COMPOUND UNDER NON-ASBESTOS CONTAINING TREAD FLOORING AND MASTIC, ON CONCRETE
- ⑥ ASBESTOS CONTAINING LEVELING COMPOUND UNDER NON-ASBESTOS CARPET SQUARES AND CARPET MASTIC, ON NON-ACM BLACK MASTIC AND CONCRETE

LEGEND

- | | |
|--|--|
| | VFT OVER 9" VAT WITH NON-ACM MASTIC |
| | 9" VAT AND NON-ACM MASTIC |
| | ELEVATED FLOORING OVER 9" VAT AND NON-ACM MASTIC |
| | CARPET SQUARES OVER 9" VAT AND NON-ACM MASTIC |
| | ACM LEVELING COMPOUND UNDER NON-ACM TREAD |
| | ACM LEVELING COMPOUND UNDER CARPET |



BUILDING NOTES


1. DRAWING IS SCHEMATIC AND MATERIAL LOCATIONS FOR ASBESTOS ARE APPROXIMATE.
2. REFER TO REPORT FOR MORE INFORMATION ABOUT THE SAMPLED OR ASSUMED MATERIALS.
3. CONCEALED AND ACCESSIBLE PIPING INSULATION ON DOMESTIC AND HYDRONIC PIPING IS ASBESTOS CONTAINING.
4. JOINT COMPOUND IN THIS BUILDING TESTED <1% (LESS THAN 1%) ASBESTOS. WA STATE DEPARTMENT OF LABOR AND INDUSTRIES (L&I) PER WISHA REGIONAL DIRECTIVE 23.30 DATED 12/28/2000. REQUIRES DEMOLITION PERSONNEL TO BE TRAINED IN ACCORDANCE WITH WAC. 296-62-0772215.
5. IN ADDITION TO THE ASBESTOS CONTAINING MATERIALS SHOWN ON THIS DRAWING, THE FOLLOWING ITEMS HAVE BEEN CONFIRMED OR ARE ASSUMED TO CONTAIN ASBESTOS:
A. DUCTWORK INSULATION
B. GASKETS
C. BASEBOARD MASTIC

SHEET NOTES

- ① ASSUMED ASBESTOS CONTAINING CORE FIRE DOOR
- ② ASBESTOS CONTAINING THERMAL INSULATION ON PIPING (INCLUDING FITTINGS)

LEGEND

- ASSUMED ACM-CORE FIRE DOOR
 ▨ TSI PIPING



APPENDIX B

ASBESTOS RE-INSPECTION FORMS

| | | | |
|--------------------------|---|------------------|--------------|
| <input type="checkbox"/> | General Services Administration Building | Building Number: | WA0811KA |
| <input type="checkbox"/> | Northwest/Arctic Region | | |
| <input type="checkbox"/> | Michelle Leach | Telephone: | 253-931-7289 |
| <input type="checkbox"/> | 400 – 15 Street Southwest, Auburn, Washington | | |
| <input type="checkbox"/> | #304 Throughout | | |

| | | | |
|--------------------------|---|--|---|
| <input type="checkbox"/> | | | |
| <input type="checkbox"/> | <input type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input checked="" type="checkbox"/> Misc. | <input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable | <input type="checkbox"/> Not Accessible |
| <input type="checkbox"/> | Carpet over 9" Vinyl asbestos tile (VAT) and non-ACM mastic on concrete | | |
| <input type="checkbox"/> | <input type="checkbox"/> Assumed ACM <input type="checkbox"/> Laboratory Analysis | ACM %: | |

| | | | | |
|--------------------------|---|---|---------------|---|
| <input type="checkbox"/> | Change from Prior Inspection: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Sample Taken: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| <input type="checkbox"/> | 91,436 SF | | | |
| <input type="checkbox"/> | 9' VAT under carpet with non-acm mastic | | | |

| | | | |
|--------------------------|--|---------------------|--|
| <input type="checkbox"/> | <input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical | Location of Damage: | <input type="checkbox"/> Localized <input type="checkbox"/> Distributed |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> 0% <input type="checkbox"/> 1 – 10% <input type="checkbox"/> 10 – 20% <input type="checkbox"/> > 25% | Overall Rating: | <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor |

| High | Medium | Low |
|--------------------------|--------------------------|--------------------------|
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Man & Rickett

13-BI-2501

Date

10/19/12

| | | | |
|--------------------------|---|------------------|--------------|
| <input type="checkbox"/> | General Services Administration Building | Building Number: | WA0811KA |
| <input type="checkbox"/> | Northwest/Arctic Region | | |
| <input type="checkbox"/> | Michelle Leach | Telephone: | 253-931-7289 |
| <input type="checkbox"/> | 400 – 15 Street Southwest, Auburn, Washington | | |
| <input type="checkbox"/> | #272 All stairwells (under vinyl tread flooring), Elevator and Cafeteria (under carpet) | | |

| | | | |
|--------------------------|--|--------|--|
| <input type="checkbox"/> | <input checked="" type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input type="checkbox"/> Misc. <input checked="" type="checkbox"/> Friable <input type="checkbox"/> Non Friable <input type="checkbox"/> Not Accessible | | |
| <input type="checkbox"/> | Leveling Compound | | |
| <input type="checkbox"/> | <input type="checkbox"/> Assumed ACM <input type="checkbox"/> Laboratory Analysis | ACM %: | |

| | | | | |
|--------------------------|-------------------------------|---|---------------|---|
| <input type="checkbox"/> | Change from Prior Inspection: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Sample Taken: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| <input type="checkbox"/> | 3,770 SF | | | |
| <input type="checkbox"/> | Leveling Compound | | | |

| | | | |
|--------------------------|--|---------------------|--|
| <input type="checkbox"/> | <input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical | Location of Damage: | <input type="checkbox"/> Localized <input type="checkbox"/> Distributed |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> 0% <input type="checkbox"/> 1 – 10% <input type="checkbox"/> 10 – 20% <input type="checkbox"/> > 25% | Overall Rating: | <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor |

| | High | Medium | Low |
|--------------------------|--------------------------|--------------------------|-------------------------------------|
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |

Mani R. Raut

Date

10/19/12

13-BI-2501

| | | | |
|--------------------------|---|------------------|--------------|
| <input type="checkbox"/> | General Services Administration Building | Building Number: | WA0811KA |
| <input type="checkbox"/> | Northwest/Arctic Region | | |
| <input type="checkbox"/> | Michelle Leach | Telephone: | 253-931-7289 |
| <input type="checkbox"/> | 400 - 15 Street Southwest, Auburn, Washington | | |
| <input type="checkbox"/> | #245 Throughout | | |

| | |
|--------------------------|--|
| <input type="checkbox"/> | |
|--------------------------|--|

| | |
|--------------------------|--|
| <input type="checkbox"/> | <input type="checkbox"/> Surfacing <input checked="" type="checkbox"/> TSI <input type="checkbox"/> Misc. <input checked="" type="checkbox"/> Friable <input type="checkbox"/> Non Friable <input type="checkbox"/> Not Accessible |
| <input type="checkbox"/> | Ductwork Insulation |
| <input type="checkbox"/> | <input type="checkbox"/> Assumed ACM <input type="checkbox"/> Laboratory Analysis ACM %: |

| | |
|--------------------------|--|
| <input type="checkbox"/> | |
|--------------------------|--|

| | | | | |
|--------------------------|-------------------------------|---|---------------|---|
| <input type="checkbox"/> | Change from Prior Inspection: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Sample Taken: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| <input type="checkbox"/> | 172 SF | | | |
| <input type="checkbox"/> | Ductwork Insulation | | | |

| | | | |
|--------------------------|--|---------------------|--|
| <input type="checkbox"/> | <input checked="" type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical | Location of Damage: | <input type="checkbox"/> Localized <input checked="" type="checkbox"/> Distributed |
| <input type="checkbox"/> | <input type="checkbox"/> 0% <input checked="" type="checkbox"/> 1 - 10% <input type="checkbox"/> 10 - 20% <input type="checkbox"/> > 25% | Overall Rating: | <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor |

| | High | Medium | Low |
|--------------------------|--------------------------|-------------------------------------|-------------------------------------|
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

M. A. Ruchent

Date

10/19/12

13-BI-2501

| | | | |
|--------------------------|---|------------------|--------------|
| <input type="checkbox"/> | General Services Administration Building | Building Number: | WA0811KA |
| <input type="checkbox"/> | Northwest/Arctic Region | | |
| <input type="checkbox"/> | Michelle Leach | Telephone: | 253-931-7289 |
| <input type="checkbox"/> | 400 – 15 Street Southwest, Auburn, Washington | | |
| <input type="checkbox"/> | #338 Throughout | | |

| | |
|--------------------------|--|
| <input type="checkbox"/> | |
|--------------------------|--|

| | |
|--------------------------|--|
| <input type="checkbox"/> | <input type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input checked="" type="checkbox"/> Misc. <input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable <input type="checkbox"/> Not Accessible |
| <input type="checkbox"/> | Gaskets |
| <input type="checkbox"/> | <input type="checkbox"/> Assumed ACM <input type="checkbox"/> Laboratory Analysis ACM %: |

| | |
|--------------------------|--|
| <input type="checkbox"/> | |
|--------------------------|--|

| | | | | |
|--------------------------|-------------------------------|---|---------------|---|
| <input type="checkbox"/> | Change from Prior Inspection: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Sample Taken: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| <input type="checkbox"/> | 8 each | | | |
| <input type="checkbox"/> | Gaskets | | | |

| | | |
|--------------------------|--|--|
| <input type="checkbox"/> | <input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical Location of Damage: | <input type="checkbox"/> Localized <input type="checkbox"/> Distributed |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> 0% <input type="checkbox"/> 1 – 10% <input type="checkbox"/> 10 – 20% <input type="checkbox"/> > 25% Overall Rating: | <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor |

| | High | Medium | Low |
|--------------------------|--------------------------|--------------------------|-------------------------------------|
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |

SM. A. Ruch

Date

10/19/12

13-BI-2501

| | | | |
|--------------------------|---|------------------|--------------|
| <input type="checkbox"/> | General Services Administration Building | Building Number: | WA0811KA |
| <input type="checkbox"/> | Northwest/Arctic Region | | |
| <input type="checkbox"/> | Michelle Leach | Telephone: | 253-931-7289 |
| <input type="checkbox"/> | 400 – 15 Street Southwest, Auburn, Washington | | |
| <input type="checkbox"/> | #379 Throughout | | |

| | | | |
|--------------------------|--|--------|--|
| <input type="checkbox"/> | <input type="checkbox"/> Surfacing <input checked="" type="checkbox"/> TSI <input type="checkbox"/> Misc. <input checked="" type="checkbox"/> Friable <input type="checkbox"/> Non Friable <input type="checkbox"/> Not Accessible | | |
| <input type="checkbox"/> | TSI Pipeline Fittings | | |
| <input type="checkbox"/> | <input type="checkbox"/> Assumed ACM <input type="checkbox"/> Laboratory Analysis | ACM %: | |

| | | | | |
|--------------------------|-------------------------------|---|---------------|---|
| <input type="checkbox"/> | Change from Prior Inspection: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Sample Taken: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| <input type="checkbox"/> | 2,015 each | | | |
| <input type="checkbox"/> | TSI pipe fittings | | | |

| | | | |
|--------------------------|--|---------------------|--|
| <input type="checkbox"/> | <input checked="" type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical | Location of Damage: | <input type="checkbox"/> Localized <input checked="" type="checkbox"/> Distributed |
| <input type="checkbox"/> | <input type="checkbox"/> 0% <input checked="" type="checkbox"/> 1 – 10% <input type="checkbox"/> 10 – 20% <input type="checkbox"/> > 25% | Overall Rating: | <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor |

| | High | Medium | Low |
|--------------------------|--------------------------|-------------------------------------|-------------------------------------|
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

J.M. Leach

Date

10/19/12

13-BI-2501

| | | | |
|--------------------------|---|------------------|--------------|
| <input type="checkbox"/> | General Services Administration Building | Building Number: | WA0811KA |
| <input type="checkbox"/> | Northwest/Arctic Region | | |
| <input type="checkbox"/> | Michelle Leach | Telephone: | 253-931-7289 |
| <input type="checkbox"/> | 400 – 15 Street Southwest, Auburn, Washington | | |
| <input type="checkbox"/> | #381 Throughout | | |

| | |
|--------------------------|--|
| <input type="checkbox"/> | |
|--------------------------|--|

| | | | |
|--------------------------|---|--|---|
| <input type="checkbox"/> | <input type="checkbox"/> Surfacing <input checked="" type="checkbox"/> TSI <input type="checkbox"/> Misc. | <input checked="" type="checkbox"/> Friable <input type="checkbox"/> Non Friable | <input type="checkbox"/> Not Accessible |
| <input type="checkbox"/> | TSI pipe run insulation | | |
| <input type="checkbox"/> | <input type="checkbox"/> Assumed ACM <input type="checkbox"/> Laboratory Analysis | ACM %: | |

| | |
|--------------------------|--|
| <input type="checkbox"/> | |
|--------------------------|--|

| | | | | |
|--------------------------|-------------------------------|---|---------------|---|
| <input type="checkbox"/> | Change from Prior Inspection: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Sample Taken: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| <input type="checkbox"/> | 2,303 linear Ft. | | | |
| <input type="checkbox"/> | TSI Pip Run Insulation | | | |

| | | | |
|--------------------------|--|---------------------|--|
| <input type="checkbox"/> | <input checked="" type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical | Location of Damage: | <input type="checkbox"/> Localized <input checked="" type="checkbox"/> Distributed |
| <input type="checkbox"/> | <input type="checkbox"/> 0% <input checked="" type="checkbox"/> 1 – 10% <input type="checkbox"/> 10 – 20% <input type="checkbox"/> > 25% | Overall Rating: | <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor |
| <input type="checkbox"/> | | | |

| | High | Medium | Low |
|--------------------------|--------------------------|-------------------------------------|-------------------------------------|
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

SM. A. Rickett

Date

10/19/12

13-BI-2501

☐

| | | | |
|--------------------------|---|------------------|--------------|
| <input type="checkbox"/> | General Services Administration Building | Building Number: | WA0811KA |
| <input type="checkbox"/> | Northwest/Arctic Region | | |
| <input type="checkbox"/> | Michelle Leach | Telephone: | 253-931-7289 |
| <input type="checkbox"/> | 400 – 15 Street Southwest, Auburn, Washington | | |
| <input type="checkbox"/> | #304 Throughout | | |

| | |
|--------------------------|--|
| <input type="checkbox"/> | |
|--------------------------|--|

| | | | |
|--------------------------|---|--|---|
| <input type="checkbox"/> | <input type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input checked="" type="checkbox"/> Misc. | <input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable | <input type="checkbox"/> Not Accessible |
| <input type="checkbox"/> | 12" Vinyl Floor Tile (VFT) with Non-ACM mastic over 9" VAT with non-ACM mastic on concrete | | |
| <input type="checkbox"/> | <input type="checkbox"/> Assumed ACM <input type="checkbox"/> Laboratory Analysis | ACM %: | |

| | |
|--------------------------|--|
| <input type="checkbox"/> | |
|--------------------------|--|

| | | | | |
|--------------------------|-------------------------------|---|---------------|---|
| <input type="checkbox"/> | Change from Prior Inspection: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Sample Taken: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| <input type="checkbox"/> | 1,330SF | | | |
| <input type="checkbox"/> | 12" Vinyl Floor Tile (VFT) | | | |

| | | | |
|--------------------------|--|---------------------|---|
| <input type="checkbox"/> | <input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical | Location of Damage: | <input type="checkbox"/> Localized <input type="checkbox"/> Distributed |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> 0% <input type="checkbox"/> 1 – 10% <input type="checkbox"/> 10 – 20% <input type="checkbox"/> > 25% | Overall Rating: | <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor |

| | High | Medium | Low |
|--------------------------|--------------------------|--------------------------|--------------------------|
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

SM. J. Ruel

Date

10/19/12

☐

| | | | |
|--------------------------|---|------------------|--------------|
| <input type="checkbox"/> | General Services Administration Building | Building Number: | WA0811KA |
| <input type="checkbox"/> | Northwest/Arctic Region | | |
| <input type="checkbox"/> | Michelle Leach | Telephone: | 253-931-7289 |
| <input type="checkbox"/> | 400 – 15 Street Southwest, Auburn, Washington | | |
| <input type="checkbox"/> | #61 Throughout | | |

☐

| | | | |
|--------------------------|--|--|--|
| <input type="checkbox"/> | | | |
|--------------------------|--|--|--|

☐

| | | | |
|--------------------------|---|--|---|
| <input type="checkbox"/> | <input type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input checked="" type="checkbox"/> Misc. | <input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable | <input type="checkbox"/> Not Accessible |
| <input type="checkbox"/> | ACM Baseboard Mastic | | |
| <input type="checkbox"/> | <input type="checkbox"/> Assumed ACM <input type="checkbox"/> Laboratory Analysis | ACM %: | |

☐

| | | | |
|--------------------------|--|--|--|
| <input type="checkbox"/> | | | |
|--------------------------|--|--|--|

☐

| | | | | |
|--------------------------|-------------------------------|---|---------------|---|
| <input type="checkbox"/> | Change from Prior Inspection: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Sample Taken: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| <input type="checkbox"/> | 612 SF | | | |
| <input type="checkbox"/> | ACM Baseboard Mastic | | | |

☐

| | | | |
|--------------------------|--|---------------------|--|
| <input type="checkbox"/> | <input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical | Location of Damage: | <input type="checkbox"/> Localized <input type="checkbox"/> Distributed |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> 0% <input type="checkbox"/> 1 – 10% <input type="checkbox"/> 10 – 20% <input type="checkbox"/> > 25% | Overall Rating: | <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor |
| <input type="checkbox"/> | | | |

☐

☐

| | High | Medium | Low |
|--------------------------|--------------------------|--------------------------|--------------------------|
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

☐

☐

| | | | |
|--------------------------|----------------------|------|-----------------|
| <input type="checkbox"/> | <u>M. A. Reebert</u> | Date | <u>10/19/12</u> |
| <input type="checkbox"/> | 13-BI-2501 | | |

| | | | |
|--------------------------|---|------------------|--------------|
| <input type="checkbox"/> | General Services Administration Building | Building Number: | WA0811KA |
| <input type="checkbox"/> | Northwest/Arctic Region | | |
| <input type="checkbox"/> | Michelle Leach | Telephone: | 253-931-7289 |
| <input type="checkbox"/> | 400 – 15 Street Southwest, Auburn, Washington | | |
| <input type="checkbox"/> | #302 Room 1551 | | |

| | | | | | |
|--------------------------|---|--|--------|--|---|
| <input type="checkbox"/> | <input type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input checked="" type="checkbox"/> Misc. | | | <input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable | <input type="checkbox"/> Not Accessible |
| <input type="checkbox"/> | Elevated Flooring over 9" Vinyl asbestos tile (VAT) and non-ACM mastic on concrete | | | | |
| <input type="checkbox"/> | <input type="checkbox"/> Assumed ACM <input type="checkbox"/> Laboratory Analysis | | ACM %: | | |

| | | | | |
|--------------------------|---|---|---------------|---|
| <input type="checkbox"/> | Change from Prior Inspection: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Sample Taken: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| <input type="checkbox"/> | 198 SF | | | |
| <input type="checkbox"/> | Elevated Flooring over 9" Vinyl Asbestos Tile | | | |

| | | | |
|--------------------------|--|---------------------|--|
| <input type="checkbox"/> | <input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical | Location of Damage: | <input type="checkbox"/> Localized <input type="checkbox"/> Distributed |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> 0% <input type="checkbox"/> 1 – 10% <input type="checkbox"/> 10 – 20% <input type="checkbox"/> > 25% | Overall Rating: | <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor |

| | High | Medium | Low |
|--------------------------|--------------------------|--------------------------|--------------------------|
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

M. J. Richert

Date

10/19/12

13-BI-2501

| | | | |
|--------------------------|--|------------------|--------------|
| <input type="checkbox"/> | General Services Administration Building | Building Number: | WA0811KA |
| <input type="checkbox"/> | Northwest/Arctic Region | | |
| <input type="checkbox"/> | Michelle Leach | Telephone: | 253-931-7289 |
| <input type="checkbox"/> | 400 – 15 Street Southwest, Auburn, Washington | | |
| <input type="checkbox"/> | #302 Mechanical 1041, 1032, 1032B, Electrical Closet, Storage Closet | | |

| | |
|--------------------------|--|
| <input type="checkbox"/> | |
|--------------------------|--|

| | | | |
|--------------------------|---|--|---|
| <input type="checkbox"/> | <input type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input checked="" type="checkbox"/> Misc. | <input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable | <input type="checkbox"/> Not Accessible |
| <input type="checkbox"/> | 9" Vinyl Asbestos Tile (VAT) and non-ACM Mastic on concrete | | |
| <input type="checkbox"/> | <input type="checkbox"/> Assumed ACM <input type="checkbox"/> Laboratory Analysis | ACM %: | |

| | |
|--------------------------|--|
| <input type="checkbox"/> | |
|--------------------------|--|

| | | | | |
|--------------------------|-------------------------------|---|---------------|---|
| <input type="checkbox"/> | Change from Prior Inspection: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Sample Taken: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| <input type="checkbox"/> | 1,820 SF | | | |
| <input type="checkbox"/> | 9" Vinyl Asbestos Tile | | | |

| | | | |
|--------------------------|---|---------------------|--|
| <input type="checkbox"/> | <input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical | Location of Damage: | <input type="checkbox"/> Localized <input type="checkbox"/> Distributed |
| <input type="checkbox"/> | <input type="checkbox"/> 0% <input type="checkbox"/> 1 – 10% <input type="checkbox"/> 10 – 20% <input type="checkbox"/> > 25% | Overall Rating: | <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor |
| <input type="checkbox"/> | | | |

| | High | Medium | Low |
|--------------------------|--------------------------|--------------------------|--------------------------|
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Jim A. Rickert

Date

10/19/12

13-BI-2501

| | | | |
|--------------------------|---|------------------|--------------|
| <input type="checkbox"/> | General Services Administration Building | Building Number: | WA0811KA |
| <input type="checkbox"/> | Northwest/Arctic Region | | |
| <input type="checkbox"/> | Michelle Leach | Telephone: | 253-931-7289 |
| <input type="checkbox"/> | 400 – 15 Street Southwest, Auburn, Washington | | |
| <input type="checkbox"/> | #258 Throughout | | |

| | |
|--------------------------|--|
| <input type="checkbox"/> | |
|--------------------------|--|

| | | | |
|--------------------------|---|--|---|
| <input type="checkbox"/> | <input type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input checked="" type="checkbox"/> Misc. | <input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable | <input type="checkbox"/> Not Accessible |
| <input type="checkbox"/> | ACM-Core Fire doors | | |
| <input type="checkbox"/> | <input type="checkbox"/> Assumed ACM <input type="checkbox"/> Laboratory Analysis | ACM %: | |

| | |
|--------------------------|--|
| <input type="checkbox"/> | |
|--------------------------|--|

| | | | | |
|--------------------------|-------------------------------|---|---------------|---|
| <input type="checkbox"/> | Change from Prior Inspection: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Sample Taken: | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| <input type="checkbox"/> | 32 Each | | | |
| <input type="checkbox"/> | ACM Core Fire doors | | | |

| | | | |
|--------------------------|--|---------------------|--|
| <input type="checkbox"/> | <input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical | Location of Damage: | <input type="checkbox"/> Localized <input type="checkbox"/> Distributed |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> 0% <input type="checkbox"/> 1 – 10% <input type="checkbox"/> 10 – 20% <input type="checkbox"/> > 25% | Overall Rating: | <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor |
| <input type="checkbox"/> | | | |

| | High | Medium | Low |
|--------------------------|--------------------------|--------------------------|--------------------------|
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

M. J. Ruffert

Date

10/19/12

13-BI-2501

APPENDIX C

AHERA BUILDING INSPECTOR CERTIFICATION

I CORP AND JOINT BASE LEWIS-MCCHORD, PUBLIC WORKS ASBESTOS CERTIFICATION

Presented By The

Environmental and Natural Resources Division

Building 2012, JBLM, WA 98433 (253) 966-1776


MARC RICKERT

Has successfully completed the requisite training, under TSCA Title II, EPA AHERA & ASHARA M.A.P.
for the following discipline:

ASBESTOS BUILDING INSPECTOR REFRESHER

CERTIFICATION NUMBER: 13-BI-2501

INSTRUCTOR:


Michael C. Roberts

Certification Date: 5/17/2012

Expiration Date: 5/17/2013

State of Florida, Provider Number 3501, Course Number 6306